


Release Notes

wylerSOFT

Version	Release Date	Release Notes
2.5.0.203	2026.06.23	Improved Detection for wylerCONNECT Rev. C
2.4.16.188	2026.01.27	Fixed version detection for wylerINSERT.
2.4.15.181	2025.07.18	Updated wybus to 2.3.14.91 (Clinotronic S support)
2.4.13.160	2025.04.07	Update wylerLicense to ensure it correctly reads dinkeyDongle
2.4.12.140	2025.06.04	- Update Firmware package to 1.0.8.8: - BlueLEVEL II Firmware update 1.0.16.0
2.4.11.134	2025.05.12	- wybus updated to 2.3.13.82 - New license request routine
2.4.10.102	2025.02.12	- New Installation routine - Improved software detection for wylerSPEC
2.4.8.74	2024.12.05	Fixed version detection for new software version.
2.4.8.71	2024.07.31	- Removed SCS and Ilac Icon - Removed link to Wyler website - Updated device firmware package to 1.0.8.4 - Read correct version of wylerPLOT
2.4.7.3	2023.11.13	- wylerExplorer 2.4.2.0 - wylerInsert 2.5.2.0
2.4.7.0	2022.12.14	wylerLICENSE update: wyerELEMENTS license is correctly on Dinkey Dongle Pro is now correctly identified
2.4.6.0	2022.11.30	GUI corrections
2.4.5.0	2022.10.31	wylerSPEC has now 12 modules
		
2.4.4.0	2022.09.26	wylerSOFT not installed automatically with other software products anymore

